

PLANNERS GROUP

ARCHITECTS+PLANNERS+DESIGNERS+ENGINEERS

SCO 4, FF, Sector 17E, Chandigarh-160017 Telephone: 0172-2703917, 2703391

www.plannersgroup.net mail@plannersgroup.net

Ref.No.PG/456/20

Date: 10.12.2020

BUILDING SAFETY CERTIFICATE

Certified that the Structural Design of Shivalik Public School at Sector 41B, Chandigarh has been done by our Organization and it conforms to all relevant Indian Standard Codes of Design for safety of building against Earthquake as per Indian Standards have been considered. The building has been constructed in our supervision as per the designs provided by us.

Further it is also certified that the undersigned conducted the inspection of Shivalik Public School, Sector 41B, Chandigarh on 05.12.2020 and found that building of aforesaid school is safe for occupants.

for PLANNERS GROUP

(PANKAS MALIK

eer No. F016495

Civil ange Chandlgarh College Chandlgarh ASSOCIATES phase-7 rea, Phase-7,

ATTESTED TO BE TRUE COPY

Principal Shivalik Public School

Chandigarn

uchian Nalua



Shivalik Public School

(Affiliated to Central Board of Secondary Education, New Delhi)

Sector 41 B, Chandigarh -160 036

Affiliation No. - 2630006, School No. 23029
Tel. No.: 0172-2626913, Fax: 0172-2629574
e-mail: shivalikchandigarh@gmail.com

No. SPS / 2020 /9796

Dated : August 11, 2020

To

The S.D.O. (Building), Estate Office, Sector 17, Chandigarh

Subject: Issuance of Building Safety Certificate in respect of Shivalik Public School, Sector 41-B, Chandigarh RCE-266

Sir,

We have to apply for the extension of affiliation of Shivalik Public School, Sector 41-B, Chandigarh to the Central Board of Secondary Education, Delhi and for this purpose Building Safety Certificate is required.

We are enclosing herewith the following documents required for this purpose to enable your office to process the case of this institution.

- Approval of Building Plan of Shivalik Public School, Sector 41-B, Chandigarh issued by Estate Office, letter No. SDO(B)/RCE-266/2837, dated 27-09-2012.
- Permission for occupancy of the school building vide letter No.SDO (B) / RCE-266/81846, dated 14-12-2020.
- Attested photocopy of Fire Safety Certificate issued by Municipal Corporation / Fire Services Department issued vide letter No. CFO/2019/957, dated 01-10-2019.
- 4. Architects visit report regarding stability of school building.

In view of above you are requested to kindly issue Building Safety Certificate in respect of Shivalik Public School, Sector 41-B, Chandigarh, at the earliest.

Thanking you,

Yours faithfully,

(D.S. Bedi) Director

Shivalik Public School Chandigarh

Encis: As above.



सम्पदा कार्यालय, यू. टी, चंडीगढ़ ESTATE OFFICE, UT, CHANDIGARH

481903

Memo. No. 389 | S / RCE-266/SDO(B)/2020

Dated 26 11-2020

To

The Director, Shivalik Public School, Sector 41-B, Chandigarh.

Regarding Shivalik Public School, Sector 41-B, Chandigarh. Subject:-

Reference your application dt. 11.08.2020 on the subject cited above.

In this regard, it is intimated that this office has no structure engineer. Accordingly, you are requested to take action at your own level by hiring a private structural engineer.

> SDO (Buildings) Estate Office,

U.T., Chandigarh.

Office: Town Hall Building, Sector 17, Chandigarh Phone: 0172-2701900, 0172-5046603