

Annexure D

BUILDING SAFETY CERTIFICATE

File No. SP-2418

Date: 5.7.23

It is certified that the existing building **Shivalik Public School** (name of the building or premises) at **Sector 41-B, Chandigarh** (address) is having Block(s) / Floor(s) as per details below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3	-	-	-	-	-

The building is owned/occupied by **Shivalik Public School run by Shivalik Educational Society (Regd.) Chandigarh** (Name of the Institution) have complied with the Building Safety requirements in accordance with National Building code Rules, and verified by the officers concerned of National Institute of Technical Teacher Training and Research (Name of Department/ Govt.) on 15.06.2023 (date of inspection) in the presence of Dr. (Mrs.) Gurkiran Jeet Nalwa, Principal, Shivalik Public School, Sector 41-B, Chandigarh (Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 5.7.23 for a period of Three year in accordance with rule and subject to compliance of the specific conditions as appended.


- 1.
- 2.
- 3.
- 4.

Issued on 5.7.23 at _____ by National Institute of Technical Teachers Training and Research, Sector 26, Chandigarh.

❖ Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Gurkiran Nalwa
Principal
Shivalik Public School
Chandigarh

Signature with Seal:



Dr. Sanjay Sharma
Professor
Civil Engineering Department
NITTTR, Sector 26, Chandigarh

Name: DR. SANJAY SHARMA

Designation: Prof. CIVIL EN.

Satwajit Kaur
Manager
Shivalik Educational Society
(Regd.) Chandigarh

Name & Address of Department/ Office: NITTTR, SEC-26, CHD.